

CONFIDENTIAL

(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

REFERENCE: [REDACTED]

ATTACHMENT TO L-2274
16 November 1966
Page 1

25X1

STATUS OF ROUTE 110
LAOS

1. SIGNIFICANCE:

ROUTE 110 IN LAOS IS OBSERVED TO BE IN A STATE OF DISUSE BETWEEN 1435N 10636E AND 1441N 10709E.

2. MISSION READOUT:

[REDACTED] REVEALS ROUTE

25X1

110 TO BE IN A STATE OF DISUSE BETWEEN 1435N 10636E (UTM XB734135), WHERE A TRAIL CROSSES THE ROAD, AND 1441N 10709E (UTM YB324261), WHERE THE ROAD IS SEVERELY WASHED OUT. ROAD INTERDICTIONS ARE NOTED AT THE FOLLOWING LOCATIONS: 1436N 10638E (UTM XB762147), 1437N 10639E (UTM XB783168), AND 1437N 10642E (UTM XB846183). NONE OF THESE INTERDICTIONS HAVE BEEN BY-PASSED. SOME MAJOR FORDS ALONG THIS ROUTE WHICH SHOW NO SIGNS OF RECENT USE ARE LOCATED AT 1438N 10642E (UTM XB847186), 1439N 10650E (UTM XB979213), 1443N 10700E (UTM YB167288), AND 1442N 10707E (UTM YB292264).

25X1

[REDACTED]
ALL UTM COORDINATES FROM AMS SERIES L7012, SHEETS 6354-IV, 6355-II, 6354-I, 6455-III AND 6455-II.

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue. For information concerning these notes contact Chief, Collateral Support Division, NPIC.

GROUP 1
Excluded from automatic
downgrading and declassification

CONFIDENTIAL

CONFIDENTIAL




NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

Approved For Release 2008/01/29 : CIA-RDP79-00849A000500050011-2

STATUS OF ROUTE 110

LAOS

25X1




14-41N 107-09E

25X1




SEVERE EROSION



14-36N 106-42E

25X1



14-41N 106-53E

25X1

REPRODUCTION OF THIS DOCUMENT IN
WHOLE OR IN PART IS PROHIBITED
EXCEPT WITH THE PERMISSION OF THE
OFFICE OF ORIGIN.

67-E-396